RAVAS ASCII PROTOCOL INDICATOR 3200



Contents

RAVAS ASCII PROTOCOL	3
Transfer Protocol	3
ASCII commands	3
Special commands 'GW' and 'SW'	5
Special commands 'AN' and 'AG'	6
Special command 'GE'	7
Explanation data lines	8
List of messages 3200 indicating device	8
Special command 'RE'	9
Special command 'GI'	10
Explanation data lines	11
Special command 'GS'	12
Explanation data lines	13
Special command 'GI'	14

RAVAS ASCII PROTOCOL

The indicator 3200 offers the possibility to communicate bi-directional with a PC or other hardware devices which can handle simple ASCII commands. (For activation of this application setting, please contact your scale dealer.)

Transfer Protocol:

Baudrate- 600 to 19200 (default = 9600)

Databits- 7 or 8 (default = 8) Stopbits- 1 or 2 (default = 1)

Parity- odd/even/none (default = none)

Handshake-none

ASCII commands*2

ASCII COMMUNICI		
ASCII command	Response string	Operation
SZ <cr></cr>	OK <cr>/ERR<cr></cr></cr>	Set zero value
RZ <cr></cr>	OK <cr>/ERR<cr></cr></cr>	Reset zero value
SP <value><cr>*1</cr></value>	OK <cr>/ERR<cr></cr></cr>	Set preset tare value
RP <cr></cr>	OK <cr>/ERR<cr></cr></cr>	Reset preset tare
RT <cr></cr>	OK <cr>/ERR<cr></cr></cr>	Reset tare
ST <cr></cr>	OK <cr>/ERR<cr></cr></cr>	Set tare
SR <cr></cr>	OK <cr>/ERR<cr></cr></cr>	Set tare (also with a previous tare) *3
SG <cr></cr>	G+0001.0 <cr></cr>	Send gross mode (continuously)
SN <cr></cr>	N+0001.0 <cr></cr>	Send net mode (continuously)
SW <cr></cr>	W+00010+000103805 <cr>*2</cr>	Send weights mode (continuously)
SA <cr></cr>	A;+000.0;+000.0 <cr></cr>	Send angle positions X and Y (continuously)
GP <cr></cr>	P+0001.0 <cr></cr>	Get preset tare
GT <cr></cr>	T+0001.0 <cr></cr>	Get tare
GG <cr></cr>	G+0001.0 <cr></cr>	Get gross
GN <cr></cr>	N+0001.0 <cr></cr>	Get net
GW <cr></cr>	W+00010+000103805 <cr></cr>	Get net, gross, status and checksum
GA <cr></cr>	A;+000.0;+000.0 <cr></cr>	Get angle positions X and Y
GE <cr></cr>	See chapter GE command	Read out of last 50 messages
GI <cr></cr>	See chapter GI command	Read out of general info and parameters
GS <cr></cr>	See chapter GS command	Read out of status and calibration
GL <cr></cr>	See chapter GL command	Read out total log file
RE <cr></cr>	See chapter RE command	Reset the ERRORs database (passcode
		required)
MN <cr></cr>	N+0001.0 <cr></cr>	Get net, wait for no motion
MG <cr></cr>	G+0001.0 <cr></cr>	Get gross, wait for no motion
RS <cr></cr>	S+0001.0;-01- <cr></cr>	Send and Reset Subtotal,
AN <cr></cr>	N+0001.0;0001 <cr></cr>	Get net and alibi nr., wait for no motion
AG <cr></cr>	G+0001.0;0001 <cr></cr>	Get gross and alibi nr., wait for no motion

- *1: If the scale is working in ranges with a number after the decimal point, the preset tare value should be given in accordingly. If the scale is working in ranges equal to or higher than 1 kg/lb, then the value should be entered with the decimal point at the end of the value. E.g. ranges 0.1/0.2/0.5 >> SP0001.5 < CR >, ranges 1/2/5/10/20/50 >> SP00150. < CR >
- *2: If an error state is reached (like overload or underload) the SW-command should be renewed after the error state has been resolved.
- *3: This is a special tare command which is mainly used with order picking applications. It cancels the previous tare and sets a new tare value which includes the old tare value and the added net weight. If the weight does not get stable within 5 seconds an error will be generated.

Special commands 'GW' and 'SW'

The 'GW' and 'SW' are commands with checksums. With these commands it is possible to get net, gross and status data. The response string does not have the decimal point information. The 'SW' update rate is slower than the other commands.

Structure of the response string:

W	+00010	+00010	38	05	<cr></cr>
Data ID	Net value	Gross value	Status(hex)	Checksum	End of string

Status bits:

Bit number	Bit definition	Status '0'	Status '1'
7 (MSB)	Indicator error	No errors	Indicator error
6	Tare active	No tare active	Tare active
5	Zero corrected	No zero correction	Zero corrected
4	Weight stable Weight unstable		Weight stable
3	Within zero range	Out of zero range	Within zero range
2	Above max load	Under max load	Above max load
1	Setpoint 2 active	Setpoint 1 not	Setpoint 1 active
		active	
0 (LSB)	Setpoint 1 active	Setpoint 2 not active	Setpoint 2 active

Example:

38 (hex) = 0011 1000(binair) bit 5, zero corrected bit 4, weight stable

bit 3, within zero range

Calculating the checksum:

The checksum is the inverted sum of all ASCII characters in the response string previous to the checksum.

Example:

Response string = W+00010+000103805<CR>

Add all hex values of the characters in the string.

[W]+[+]+[0]+[0]+[0]+[1]+[0]+[+]+[0]+[0]+[0]+[1]+[0]+[3]+[8]

Total is 2FA(hex)

Remove the most significant digit, result is FA(hex)

Invert the hexadecimal value, result is 05(hex)

Convert the hexadecimal value to characters, result is [0][5]

Special commands 'AN' and 'AG'

With these special commands an extra value is sent together with the weight; the alibi number. It consists of 4 digits and is also saved in the indicators alibi memory. The number increases with every stored weighing.

The command works as follows:

- PC or terminal sends out the command AN or AG for demanding the net or gross weight respectively.
- Indicator waits for the weight to become stable after which it returns the demanded weight accompanied by the alibi number under which this weighing was stored in the alibi memory of the indicator. The indicator display will show the weight and alibi no. stored 3x repeating after which it returns to the weighing mode. The subtotal is added in the background.
- Format of the return string is: N+0001.0;0001<CR> or G+0001.0;0001<CR> N = Net indicator
 + = sign indicator
 0001.0 = weight value with decimal point
 ; = semi-colon separator sign
 0001 = alibi number
 <CR> = ending sign

NOTE: in case of an error in the display the PC will receive the following strings instead of a weight:

Error display*1	Error Response string	Meaning
Overload	0000000 <cr></cr>	Above full scale
Underload	===== <cr></cr>	Gross below zero range
Underload	===== <cr></cr>	Underload on AD converter
Overload	0000000 <cr></cr>	Overload on AD converter
	===== <cr></cr>	out of level

^{*1:} All error messages can only be resolved at the weighing system.

Special command 'GE'

With this command the last 50 errors of P93 can be read out. In these 50 errors only the most important user errors, like tip-loading or side-loading handling errors are taken into consideration. Other errors are summed up and will follow after the 50 errors have been sent.

The transmission will be completed by sending out a form feed <FF>.

Command	Function	Response indicator									
GE <cr></cr>	Get Errors: Retrieve	1	2	3	4	5	6	7	8	9	10
ASCII dec. value G =	the last 50 messages	0	1	;	0	2	;	date	;	time	
071	and the number of	0	2	;	7	1	;	date	;	time	
ASCII dec. value E =	times that a message	0	3	;	0	1	;	date	;	time	
069	has been displayed	5	0	;	7	1	;	date	;	time	
			ı	ĺ	ı	ı	et	cetera			
		0	4		0	0	0	5			
		7	2	:	0	0	2	5			
ASCII dec. value <ff> = 012</ff>	A sequence of data rows follows until the complete register is read. The data dump is closed by a Form Feed <ff></ff>	01;0 02;7 01;0 02;0 03;0 04;0 06;0 09;0 10;0 22;0 23;0 24;0 41;0 42;0 44;0 45;0 60;0 61;0 92;0 99;0 99;0 81;0 97;0 97;0 98;0 99;0	1;23 1;23 000 001 000 000 000 000 000 000 016 000 000	0218	3;112	<mark>23</mark>					

Explanation data lines

01;02;<mark>030218;1254</mark> =

0	1	;	7	1	<mark>date</mark>	<mark>;</mark>	<mark>time</mark>
reg	ister	Separation	messa	ge no.	<mark>Date in</mark>	Separation	Time in
no	٥.	sign	displa	yed	<mark>format</mark>	<mark>sign</mark>	format hhmm
					<mark>ddmmyy</mark>		

The first retrieved from the database of P93 was the "71" which stands for tip-load handling.

72;0025 =

7	2	;	0	0	2	5
message	e no.	Separation sign	N	d		

^{&#}x27;72', which stands for side-load handling, was registered 25 times since the unit has been put in the field.

List of messages 3200 indicating device

function	Log Nummer	Disp Txt
LOAD CELL SIGNAL UNSTABLE	1	"Err01"*
IFORKS OVERLOADED ON MAXIMUM CAPACITY	2	"Err02"*
TARA WHILE NEGATIVE WEIGHT	3	"Err03"
ZERO OUT OF RANGE	4	"Err04"
IFORKS OVERFLOW ADC	6	"Err06"*
CALIBRATION OUT OF RANGE NEGATIVE	8	"Err08"
CALIBRATION OUT OF RANGE SIGNAL TOO LOW	9	"Err09"
CALIBRATION POINT LOWER THAN PREVIOUS POINT	10	"Err10"
COMMUNICATION FAILURE FORK 1	21	"ErrF1"
COMMUNICATION FAILURE FORK 2	22	"ErrF2"
COMMUNICATION FORK 1 TOO FEW SAMPLES received	23	"Er_F1"
COMMUNICATION FORK 2 TOO FEW SAMPLES received	24	"Er_F2"
COMMUNICATION FAILURE 1AD	25	"ErrAd"
COMMUNICATION 1AD TOO FEW SAMPLES received	26	"Er_Ad"
LEVEL MAX	40	"Err L"
OIML restriction while printing	41	"OlnnL"
NTEP restriction while printing	42	"ntEP"
OIML restriction while calibration	43	"OlnnL"
NTEP restriction while calibration	44	"ntEP"
CALIBRATION NOT ALLOWED PROTECTED BY JUMPER	45	"Cal-J"
AUDITTRAIL OUT OF RANGE	46	"SCall"
LOW BAT INDICATOR	60	
LOW BAT FORK 1	61	F1 💟
LOW BAT FORK 2	62	F2 🔼
OFF CENTRE LOAD TIP (only active when P13 ≠ no)	71	"tiP"*

OFF CENTRE LOAD SIDE (only active when P13 ≠ no)	72	"SidE"*
ERROR in RDC transfer	80	"trErr"
RDC buffer full	81	"FULL"
GROSS NEGATIVE UNDERLOAD	92	""
CALIBRATION POINT MUST BE HIGHER THAN PREVIOUS ONE	98	"Err98"
ZEROING WHILE UNIT SWITCHED	99	"Err99"

^{*:} these errors are registered only in the P93 database.

Special command 'RE'

With this command the list of errors can be reset to none. For this a password is required.

Command	Function	Res	por	ise i	indi	cato	r				
RE <cr></cr>	Reset Errors: Reset the	1	2	3	4	5	6	7	8	9	10
ASCII dec. value G = 082	error messages	Р	Α	S	S	W	0	R	D	?	
ASCII dec. value E = 069											
5220 +←	Password and Enter	0	K								

Special command 'GI'

With this command the firmware versions of all the $\mu P's$ can be read out and all the settings of the parameters will be listed, after which the transfer is ended by sending the form feed command <FF>.

Command	Function	Response indicator
GI <cr></cr>	Get Info: Read out the	1 2 3 4 5 6 7 8 9 10
ASCII dec. value G = 071	general data as	S T M; V 0 . 6
ASCII dec. value I = 073	firmware versions and	N R F M ; V 0 . 2
	parameter settings	P 0 1 ; 0 1
		Etcetera
ASCII dec. value <ff> = 012</ff>	A sequence of data rows follows until the complete register is read. The data dump is closed by a Form Feed <ff></ff>	P 9 9 ; X X X X X X X X X

DOZO,VEC
P070;YES
P071;100
P072;015
P080;0
P081;1.000
P082;1.000
P083;1.000
P084;1.000
P085;1E39Cd-7C82C7
P096;1
P098;001
P122;00
P124;01
P125;20
P126;100
<ff></ff>

Explanation data lines

STM; V0.22 =

S	Т	М	;	V	0		2	2
main p	rocesso	r STM	Separation		Fi	rmware ve	rsion	
			sign					

The firmware version of the main processor of this device is V0.22.

NRFM;V0.3_t = Firmware version of the BLE-Master processor of the iForks receiver module is V0.3 t.

NRFS; V0.7 = Firmware version of the BLE-Slave processor on the main board is V0.7.

NRFT1;V0.7 = Firmware version of the BLE processor of the iForks transmitter module 1 is V0.7.

NRFT2;V0.7 = Firmware version of the BLE processor of the iForks transmitter module 2 is V0.7.

M	а	С	S	;	Α	В	С	1	2	3	
Mac address Bluetooth Slave Separation				Separation	Mac address						
(fixed	on ma	inboard)	sign							

The Mac addresses of the Bluetooth modules are given.

MacS; ABC123 = Mac address of the Bluetooth Slave (placed directly on the main board).

Mac1; ABC123 = Mac address of the Bluetooth Fork1 (placed on the iForks transmitter module 1).

Mac2; ABC123 = Mac address of the Bluetooth Fork2 (placed on the iForks transmitter module 2).

P01;01 =

Р	0	1	;	0	1
	Parameter	no.	Separation sign	Setting of the	e parameter

Parameter 01 was set on value 01 which stands for the start-up unit of the device. In this example that would be 'kg'. For the complete parameter list please see the PI-3200 doc.

Special command 'GS'

With this command the status of the device can be read out and information will be given about the calibration values and the last time a calibration and/or parameter setting had taken place. The data transfer will be ended with a form feed <FF>.

Command	Function	Response indicator										
GS <cr></cr>	Get Status: read	1	2	3	4	5	6	7	8	9	10	
ASCII dec. value	out the status	V	F	1	;	3	•	6	٧			
G = 071	and calibration	V	F	2	;	3	•	5	٧			
ASCII dec. value	information of	V	F	Ι	;;	1	2		6	٧		
S = 083	the device											
		L	С	1	;	±	1	2	3	4		
		L	С	2	;	±	1	2	3	4		
						1	Eto	cete	ra			
		G	S	3	;	±	1	2	3	4		
ASCII dec. value <ff> = 012</ff>	A sequence of data rows follows until the complete register is read. The data dump is closed by a Form Feed <ff></ff>	LC1; LC2; LC3; LC4; GS0 GSA GS1 GS2 GS3 GSC CP0; CP2; CP3 CP1; CP2 CP3 Corf Corf Corf Corf Corf Corf	4.0 13.2 0185;-000 ;-000 ;-000 ;-000;-000;-000;-000;	1;+00 90.27 9 53 19 50;+0 1065; 500;+ 000;+ 000;+ 000;+ 0000 0000 000	.0000 -000 1029 0000 0000 0000	.00 00;+0 1074; 207;+ 000;+ 000;+	.000 -000 -1029 -000 -000 -000	1271 9207 9000 9000 9000	;-00 ;+10; ;+00 ;+00 ;+00	0147 2920 0000 0000 0000	0 7;+10; 0;+00; 0;+00; 0;+00;	00;+00.000000 29207;00704.74 00000;00000.00 00000;00000.00 00000;00000.00 00000;00000.00

Explanation data lines

VF1;4.0V =

Supply voltage of Fork1 is given in Volts.

VF2;4.0V =

Supply voltage of Fork2 is given in Volts.

VFI;13.2V =

Supply voltage of the indicator is given in Volts.

W±12345;G±123.12 =

The actual displayed weight in basic units (P01 depending) and present level in grades(°) are given.

LC1;±1234567 =

The actual number of AD counts of load cell input 1 is given.

LC2;±1234567 =

The actual number of AD counts of load cell input 2 is given.

LC3;±1234567 =

The actual number of AD counts of load cell input 3 is given.

LC4;±1234567 =

The actual number of AD counts of load cell input 4 is given.

GS0;±XXXX;±YYYY;±ZZZZ =

The calibrated X,Y and Z values of the G-sensor (iFork) are given at zero degrees and zero load.

 $GSA0;\pm 123.12;\pm 123.12 =$

The calibrated values of raw X and raw Y at 0 calibration of the CS001 correction sensor (1AD) are given.

GS1;±1234 =

The actual number of AD counts of G-sensor direction 1(X) is given.

GS2;±1234 =

The actual number of AD counts of G-sensor direction 2(Y) is given.

GS3;±1234 =

The actual number of AD counts of G-sensor direction 3(Z) is given.

GSC;±1000;±1.12345; ±1.12345; ±1.12345; ±1.12345;12.123456;

The used calibration weight, the compensation factors for P1, P2, P3 and P4 and the level offset are given in this order {Cal_Weight};{P1_Comp}, {P2_Comp}; {P3_Comp}; {P4_Comp};{Loffset_kg}.

CP0;±1234567; ±1234567;±1234567; =

The AD counts of the 4 LC's at 0 kg of the original calibration are given. The first count is from LC-A, the second count is from LC-B etc.

CP1U;12345; ±1234567;±1234567;±1234567;±1234567;12345,12 =

The first calibration point up, the AD counts of the 4 LC's at the first calibration point and the gain factor are given.

CP2U;12345; ±1234567;±1234567;±1234567;±1234567;12345,12 =

The second calibration point up, the AD counts of the 4 LC's at this calibration point and the gain factor are given.

CP3U; 12345; ±1234567;±1234567;±1234567;±1234567;12345,12 =

The third calibration point up, the AD counts of the 4 LC's at this calibration point and the gain factor are given.

CP1D; 12345; ±1234567;±1234567;±1234567;±1234567;12345,12 =

The first calibration point down, the AD counts of the 4 LC's at this calibration point and the gain factor are given.

CP2D; 12345; ±1234567;±1234567;±1234567;±1234567;12345,12 =

The second calibration point down, the AD counts of the 4 LC's at this calibration point and the gain factor are given.

CP3D; 12345; ±1234567;±1234567;±1234567;±1234567;12345,12 =

The third calibration point down, the AD counts of the 4 LC's at this calibration point and the gain factor are given.

CorA;12.123 =

The correction factor at the original calibration for corner A is given

CorB; 12.123 =

The correction factor at the original calibration for corner B is given

CorC; 12.123 =

The correction factor at the original calibration for corner C is given

CorD; 12.123 =

The correction factor at the original calibration for corner D is given

CF;00;061017;1533 =

Present audit trail number for the parameter setting with the time stamp

CA;00;061017;1533 =

Present audit trail number for the calibration with the time stamp

Special command 'GL'

This command is used to retrieve all data of the commands 'GE', 'GI' and 'GS' combined in one dataflow without the form feeds in between but only a form feed at the end.

So the response would be the response at 'GE' minus the form feed, followed by the response at 'GI' minus the form feed, followed by the response at 'GS' with the form feed.