HOVMAND
LIFTING & MOVING TECHNOLOGY

Mounting tools on Hovmand lifters

The mounting plate (sledge) is fitted with 6-12 holes M6 or M8. Screws must not go more than 3 mm through the sledge.



Please make sure the surface of tool fixation is completely flat where it is mounted to the sledge. Otherwise it may affect the angles of the sledge and cause unstable lowering or lifting.