





1a

1000-1500-2000






1b

1000-1500-2000






2a

2500



2b

2500



3a

1000-1500-2000



 M8x16

 5

 20 Nm
± 15%

 M8

 13



3b

2500



 M8x16

 5

 20 Nm
± 15%

 M8

 13



4a

1000-1500-2000



 M8x16

 5

 20 Nm
±15%

 M8

 13



4b

2500

 M8x16

 5

 20 Nm
±15%

 M8

 13

